

FIG. 3a





FIG. 4a





FIG. 5a





FIG. 6a

202210-09115001





FIG. 7






FIG. 9




FIG. 10

METERING PUMP WITH PROPORTIONAL OUTPUT




FIG. 11




FIG. 12




FIG. 13

[illegible]

FIG. 14




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 18a




FIG. 18b




FIG. 18c




FIG. 19




FIG. 19a




FIG. 19b




FIG. 19c




FIG. 20




FIG. 21









FIG. 22







09850-013001



2022FD-054T500T




FIG. 26

202210"0911500F




FIG. 28




FIG. 28a





FIG. 28b



2022-09-09 09:50:40




FIG. 29




FIG. 29a

FIGURE EIGHT MOTION OF PISTON ARMS
 CROSS U-JOINT, WORST CASE DEVIATION






FIG. 30



202210-09415001




FIG. 32





FIG. 32a



2022FO-0985001






FIG. 34

2022-10-09 15:00






FIG. 36




FIG. 37

2022-09-09 10:54:16.013001




FIG. 38

FIG. 38A





FIG. 38B



202210-09115001




FIG. 40

202207034T500F






FIG. 41

[illegible]








FIG. 44

2022FO/031T500F

FIG. 45





FIG. 46






FIG. 47




FIG. 48




FIG. 49

202610-09850-013001




FIG. 50




FIG. 51




FIG. 53

2022100915001




FIG. 52




FIG. 54




FIG. 55

20250109 09:50:05




FIG. 56

FIG. 56B




FIG. 56A








FIG. 56C





202210-034500F




Fig. 57

[illegible]




Fig. 58




Fig. 58

09850-013001